


SLOPE MAP

- SLOPES GREATER THAN 20%
- SLOPES 10% TO 20%
- SLOPES 5% TO 10%
- SLOPES LESS THAN 5%

DESIGN ISSUES

- Step Slopes
- Site Drainage
- (ADA) Accessibility
- 5% grades along pathways
- SPU
 - Reservoir roof
 - Chlorine bldg.
 - Mechanical vault
 - Maintenance & Vehicle Access
 - Water towers
 - Retaining wall
 - Underground utilities
- Security & Safety
 - SPU facilities
 - Residential backyard security
 - Visibility from street & neighbors
- Connections
 - Across 35th Avenue SW
 - Between upper Myrtle St. Viewpoint & Park
 - West side alleyway



1.22.2008



DESIGN ISSUES MYRTLE RESERVOIR PARK